

The package includes:

T.B.APOLLISH fan * 1 , Screws * 4 , 3 pin to 4 pin adaptor * 1

Installation

- 1. PC power off at all times during installation
- 2. Please refer to Figure A for the airflow directions
- 3. Install the fan on the case with the screws and repeat the action until finish the installation



4. Connect the 3 pin connector to a specific 3 pin 12V header on the motherboard. Or attach the enclosed 3 pin to 4 pin adaptor to your power supply



3 pin connector

Figure A Airflow direction Airflow direction Rotation UCTA8/9/12/14 N - BL/R

Detaching the fan blades

Carefully push out the fan blades with your thumbs in the inner area





Reattaching the fan blades

Press the center of the blades towards the frame until it clicks

